



**NUMBER:** 08-013-17 REV. A

**GROUP:** Electrical

**DATE:** February 04, 2017

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-013-17, DATED FEBRUARY 03, 2017, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE A NOTE ABOUT THE S33 RECALL AND CHANGE TO AN INFORMATION ONLY BULLETIN.**

**NOTE: **\*\*JK (Wrangler) Clockspring related concerns are addressed within the RC-S33-16 Recall.\*\*****

***SUBJECT:***

Clockspring Replacement Due To Airbag Warning Lamp Illumination (X41) Warranty Extension

***MODELS:***

2007                      (JK)                                      Wrangler

***DIAGNOSIS:***

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

***POLICY:***

Information only.

**NOTE: See Warranty Bulletins: U.S. D-15-23, Canada SAB-2015-20, Mexico BG-47-15, International ID-15-08 or Puerto Rico/Virgin Islands ID-15-09 for details associated with the extended warranty.**