

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: November 30, 2018
TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers
RE: Lancer Passenger Side Frontal Air Inflator – Safety Recall Campaign – Revised
TIN NO. TIN-16-SR-002-B

.....

AFFECTED VEHICLES: 2006 – 2007 Lancer

PURPOSE

Replacement part # 7030A844 for SR-16-002, "Lancer Passenger Side Frontal Air Bag Inflator – Safety Recall Campaign," has been discontinued and is being superseded by part # 7030A977. A revised bulletin, SR-16-002REV, "Lancer Passenger Side Frontal Air Inflator – Safety Recall Campaign – Revised," is being released today, to provide instructions for the installation of part # 7030A977. The installation instructions have changed to apply specifically to part # 7030A977. **Please ensure the new instructions are reviewed prior to installation of part # 7030A977.** No notification letters are being mailed to owners as a result of this bulletin revision.

- **If campaign C1603A was performed using part # 7030A844 on a vehicle on or prior to today, November 30, 2018, the recall claims must be entered into the Warranty system by December 14, 2018.**
- **Repairs made after December 4, 2018, using part # 7030A844, on vehicles that have not had the recall already completed, will not be eligible for reimbursement.**

Please see Parts Bulletin OP-LN-01-18 for instructions on returning unused part # 7030A844 in your inventory.

Some Authorized Mitsubishi Motors dealers have been force allocated new inflator part # 7030A977 stock based on their on-hand inventory of inflator part # 7030A844. Parts shipments were processed via the 'R' order type and started shipping along with your scheduled stock order beginning 11/29/2018. Dealers may place additional orders via the MDL. Please refer to Parts Bulletin OP-LN-01-18 for additional information.

Dealers must review the Warranty Superscreen to confirm if any vehicles in their new or used vehicle inventories are affected, and conduct this campaign prior to delivering them. When checking for applicability of this campaign (C1603A), please check for and complete any other open campaigns. Always obtain the customer's approval before completing a campaign on a customer owned vehicle.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is sold/delivered. Dealers must check their inventory vehicles' VINs on the Warranty Superscreen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to sell/deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.