

[Next Unread Message](#)[View Message](#)

Sent on	11	09	2016	Expires on	11	25	2016
From	Motorcycle National Field Service						
Subject	Service Bulletin GL1800 #24 - Verifying Affected Units						

As stated in the AFFECTED UNITS section of *Service Bulletin GL1800 #24* only *certain* model year 2006-2010 GL1800-8A (Airbag type) motorcycles are affected by this recall. In other words, not all units within the expressed model year range are affected.

Some dealers have mistakenly repaired units that are not affected by this recall.

As with any Honda Service Campaign you should always check *iN Unit Information* to verify if a unit is affected by a campaign before performing the repair procedure.

SERVICE BULLETIN

The AFFECTED UNITS section of *Service Bulletin GL1800 #24* has been revised to include specific instructions on how to determine if a unit is affected by this recall. Please make sure that all service staff are using the "*Revised November 9, 2016*" edition of this bulletin.

Service Bulletin GL1800 #24 – REVISED November 9, 2016

If you have any questions, please contact Motorcycle TechLine through TechLine Connect on *iN*, or call TechLine at (800) 421-1900, option 9; or contact your District Service Manager.

Thank you,
American Honda Motor, Co., Inc.

Bradley Little
Manager, National Field Service
Motorcycle Division

Bulletin #: 16-0316