SAFETY RECALL





Takata Passenger Airbag Inflator Voluntary Safety Recall Campaign

> Reference: PM656 Date: January 27, 2016

Attention: Dealer Principal, Sales, Service & Parts Managers

UPDATE January 27, 2017

The announcement from October 6, 2016 has been superseded.

- Interim part number: 98561-EM38E is no longer available and is now restricted
- All open parts orders will be cancelled as Nissan cannot obtain this part any longer from Takata
- PM656 will be turned off in service comm effective January 28, 2017
- Vehicles subjected to this campaign that are still not remedied as well as vehicles that received interim repairs can now be identified in Service Comm under Campaign I.D. PM 657

Please refer to the campaign announcement for PM657 for additional details and discard previous versions of the campaign announcement for PM656.

- Q: I have a small supply of 98561-EM38E on my shelf. What do I do with those parts?
- A. A limited amount of parts still remain in dealer inventory. If an owner presents a notification letter for PM656 matching their VIN, dealers may use these parts until they are gone.

If performing an interim repair, dealers must claim the repair under PM656. Dealers should use the following claims information when using 98561-EM38E and follow repair instructions in NTB16-032.

Submit a "CM" line claim using the following claims coding:

CM I.D.	DESCRIPTION	OP CODE	FRT
PM656	Remove and Replace Passenger Front Airbag Inflator 2007-11 Versa Sedan	PM6560	0.9 hrs.
PM656	Remove and Replace Passenger Front Airbag Inflator 2007-11 Versa Hatchback	PM6561	0.8 hrs.

Expense

Sublet Code / Name	Qty (Max)	Required / Optional		
502 Rental	\$40.00 @ 10 Days (\$400 MAX)	Optional		
Contact the Warranty claims call center 1-800-258-7008 Option 7, if additional expense is required.				
Shorting Pin	Napa Item #784566 or Grainger Item # 4YT50	Optional (\$0.50 MAX)		

Part numbers are required on warranty claims submitted

NISSAN NORTH AMERICA, INC.

Aftersales DIVISION