

# Takata Inflator Applicability and NEW Order Process – TKA,TKB,TKC

TO: Parts Managers/Service Managers  
FROM: Subaru of America, Inc.  
DEPARTMENT: Parts & Service  
DATE: 09/29/2016

---

**\*\* Current repair procedures are being finalized. Please refrain from doing any repairs or contacting any customers for this part until the approved procedure is posted on STIS.**

Please refer to the below Applicability Chart for the TKA, TBC and TKC Takata recall when ordering inflators.

Please check RPM for recent inflator shipments for rental authorizations.

| <b><u>Application</u></b>                  | <b><u>Part Number</u></b> |
|--|---------------------------|
| 2003-2004 Legacy / Outback; 2003-2006 Baja | 98279AE00A                |
| 2005-2009 Legacy / Outback                 | 98279AG00A                |
| **2009-2011 Forester                       | 98279SC010                |
| **2008-2011 Impreza /WRX /STI              | 98279FG010                |
| **2010-2011 Legacy / Outback               | 98279AJ02A                |
| **2006-2007 Impreza / WRX / STI            | 98279FE160                |
| **2006-2011 Tribeca (available 12/2016)    | 98279XA02A (pending)      |

### **New Recall Parts Order Process with Updated Parts Listing**

Starting October 3<sup>rd</sup> part numbers will be available for retailer order input through the **NEW Recall Parts Order Process** designated for recall parts in restricted supply:

1. All orders **MUST** be input through PRIME ordering only (orders input through DMS or RPM will **NOT** be accepted)
2. Maximum inventory on-hand/in-transit/on-order quantity will be set for retailers according to 'Dealer Level' as posted in RPM/Marketing Inquiry screen
3. PRIME will accept replenishment orders up to the amount of maximum quantity setting (Maximum quantity levels will be adjusted as flow of incoming SOA inventory increases)

Below is the initial maximum quantity setting for restricted Takata airbag inflators by 'Dealer Level' by Part Number:

| <b>Dealer Level</b> | <b>WQR53</b> | <b>98279FE070</b> | <b>98279AG00A</b> | <b>98279AE00A</b> | <b>98279AJ02A</b> | <b>98279SC010</b> | <b>98279FE160</b> | <b>98279FG010</b> |
|---------------------|--------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|
| 1                   | 2            | 2                 | 1                 | 1                 | 1                 | 1                 | 1                 | 1                 |
| 2                   | 3            | 3                 | 2                 | 2                 | 2                 | 1                 | 1                 | 1                 |
| 3                   | 5            | 5                 | 3                 | 3                 | 3                 | 1                 | 1                 | 1                 |
| 4-5                 | 8            | 8                 | 4                 | 4                 | 4                 | 2                 | 2                 | 2                 |

Retailer input orders will be accepted starting Monday, 10/3, only through PRIME. (PartsEye)  
Please check "Hot Topics" for additional process details. **Any existing orders for above part numbers not shipped as of Friday 9/30 will be cancelled.**

SOA will maintain a weekly exception report to monitor compliance to this new order process.