



Date: July 01, 2016
To: Audi Dealer Principal, Service Manager, Warranty Administrator, Sales Manager, General Manager & Parts Manager
From: Audi Customer Protection
Subject: Updated Information and Recall Code Visibility - USA
Safety Recall 69O2 – Takata Front Passenger Frontal Airbag Inflator

This is an update to the safety recall communication on Takata front passenger airbag inflators sent on June 01, 2016.

- Audi has assigned the code **69O2** to vehicles affected by this safety recall.
- On or about July 02, 2016 affected vehicles will be identified in VIN lookup with the status **REPAIR NOT YET AVAILABLE**.
- Repair information will be provided to dealers when parts and repair instructions become available to support this recall.

IMPORTANT REMINDER ON VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Audi Public Relations.

Audi Customer Protection