

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4665
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 1, 2018

Subject: 15808C – Noncompliance Recall Revised
No Key in Reminder Chime and/or No Audio

52320-02 – Noncompliance Recall Revised
Instrument Panel Cluster Park Brake Tell Tale Lettering Height

17130E - Noncompliance Recall Revised
Loss of Key Reminder Chime

39440-02 – Noncompliance Recall Revised
Electronic Brake Control Module Memory Failure

15272B – Emission Recall Revised
Carbon Monoxide Emissions

15176E - Noncompliance Recall Revised
Sunroof Switch Compliance

15819-02 - Noncompliance Recall Revised
Vehicles Built Without Tire Pressure Monitoring System (TPMS) -
USA Only

45340-04 - Noncompliance Recall Revised
BYOM1 Lockup with Loss of Key Chime

15240E – Safety Recall Revised
Power Lift Gate Prop Rod Recovery

15299D – Safety Recall Revised
Driver Side Rear Pillar Interior Fires

Models: Bulletin 15808B: 2016 Chevrolet Camaro, Malibu, Silverado,
2016 GMC Sierra Equipped with Radio Infotainment System (RPO
IOA/IOB)

Bulletin 52320-01: 2016-2017 Cadillac CT6, CTS, Escalade,
Escalade ESV, XTS

Bulletin 17130D: 2013-2016 Chevrolet Sonic, Trax, 2013-2015 Chevrolet Spark equipped with a Bring Your Own Media ("BYOM") (RPO UF7) Radio

Bulletin 39440-01: 2016 Chevrolet Malibu

Bulletin 15272A: 2009-2011 Buick Lucerne Equipped with 3.9L Engine (RPO LGD)

Bulletin 15176D: 2013-2015 Chevrolet Malibu Equipped with Power-Operated Roof Panel System (RPO CF5)

Bulletin 15819-01: 2014-2016 Chevrolet Express (Incomplete Van w/159" Wheelbase), 2014-2016 GMC Savana (Incomplete Van w/ 159" Wheelbase)

Bulletin 45340-03: 2016 Chevrolet Aveo (Export Only), 2015-2016 Chevrolet Sonic, 2016-2017 Chevrolet Sonic (Export Only), 2013-2015 Chevrolet Spark, 2016-2017 Chevrolet Tracker (Export Only), and 2015-2016 Chevrolet Trax Equipped with a Bring Your Own Media 1 ("BYOM1") Radio

Bulletin 15240E: 2008-2012 Buick Enclave, 2009-2012 Chevrolet Traverse, 2007-2012 GMC Acadia, 2007-2010 Saturn Outlook Built Prior to March 10, 2012, Equipped with Power Lift Gate (TB5 or E61)

Bulletin 15299D: 2013-2016 Cadillac ATS Sedan

To: All General Motors Dealers

The Service Procedure and the Warranty Information sections have been revised. Effective immediately, technicians MUST record the Warranty Claim Code on the Job Card. To avoid warranty transaction rejection, this information must be entered when submitting the transaction. If the Same Calibration/Software Warning is noted on the SPS Controller screen, continue with the programming event using SPS to ensure a Warranty Claim Code is displayed on screen. Please discard all previous copies of the subject bulletins.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS