

# Thor Motor Coach Recall Repair Instructions



Recall # 16V-492

Description/Title: **2017 Outlaw 37RB and 37BG Fuel Dispensing Warning Label**

Affected Product Line(s): **Certain 2017 Outlaw 37RB and 37BG Units**

Service Campaign # : **RC000120**

Released Date: **8.08.15**

Failure Code: **TMCRC80451V**

Document Date: **8.08.15**

Time Allowed: **0.2 hr**

Document Revision: **A**

## Instructions:

### 1. Open the rearmost compartment door on the driver's side of the unit



2. Clean the back of the compartment door to make sure there is no dirt or other residue on it.
3. Apply the warning label to the newly cleaned surface. Make sure that the label is not wrinkled.
4. Close the compartment door before moving the vehicle.