



NHTSA Safety Recall 16V-____

TO: Winnebago Industries, Inc. Dealers

SUBJECT: Campaign #141 – Truma W/H Grommet

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2017 model year Winnebago View® and Itasca Navion® motorhomes.

These motorhomes were manufactured November 16, 2015 through June 23, 2016. The LP line grommet in the Truma W/H was not installed correctly. There is potential for carbon monoxide to enter through this grommet opening and into the cabin. Carbon monoxide is an odorless, colorless gas which may build up enough in an enclosed space resulting in serious symptoms or death.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Winnebago Industries, Inc. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward.

Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

TO113 US/1

INSTRUCTION TO PERFORM CAMPAIGN #141

Affected Models:

Certain 2017 model year Winnebago View® and Itasca Navion® motorhomes.

Repair Procedure:

Refer to the instruction sheet for sealing the water heater grommet.

Parts Information:

Use a polyurethane (silane modified polymer-based sealant/adhesive). If additional parts are needed for a retail customer, contact Winnebago Industries, Inc., Attention: Recall Administrator at (800) 628-7692.

REIMBURSEMENT

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

	<u>OPERATION NUMBER</u>	<u>TIME ALLOWANCE</u>
SEALING WATER HEATER GROMMET	24410101	_____

Thank you for your cooperation.

Winnebago Industries, Inc.
Forest City, Iowa 50436

TO113 US/2

Enclosures