

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Recall 16V-XXX: Check and Replace Driveshaft
Date: Friday, July 15, 2016 4:02:02 PM

Publish Date: July 15, 2016
From: Technical Service
Expiration Date: July 29, 2016

DCSnet Message
Urgent



Subject: Recall 16V-XXX: Check and Replace Driveshaft

BMW AG is conducting a Voluntary Safety Recall involving the certain 2015 Model Year M5, M6 coupe, convertible, grand coupe vehicles regarding the Driveshaft. Attached is Service Information bulletin B26 04 16 for more details.

At this time, a repair solution is being developed. You will be updated when additional information becomes available.

Affected vehicles can be identified under "open campaign" in DCS Warranty Vehicle Inquiry or ISPA Light with the description: 0026280100 Recall B260416 No repair available Driveshaft

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Sincerely,

Technical Service

Attachments:



Recipients: BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel





SI B26 04 16
Driveshaft

July 2016
Technical Service

Recall 16V-XXX: Check And Replace Driveshaft

MODEL

F06 (M6 Grand Coupe)	F10 (M5 Sedan)	F12 (M6 Convertible)	F13 (M6 Coupe)
----------------------	----------------	----------------------	----------------

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving certain 2015 Model Year M5, M6 coupe, convertible, grand coupe vehicles produced from September 2014 through December 2014. The driveshaft may have been produced out-of-specification. An inadequate weld could result in a crack in the driveshaft. Over time, this could lead to further damage to the driveshaft. Ultimately, drive torque would no longer be transmitted to the rear wheels.

Approximately 956 vehicles may be affected.

Affected vehicles can be identified under “Open Campaign” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

0026280100 Recall B260416 No repair available Driveshaft

This bulletin will be updated with repair instructions, parts and warranty information when they become available.

ATTACHMENTS

View PDF attachment [B260416Q&A](#).

View PDF attachment [Recall Notice B260416](#).

[Copyright ©2016 BMW of North America, Inc.]