

Thor Motor Coach Recall Repair Instructions



Recall # 16V-571

Description/Title: **SAE Shower Door Curtain**

Affected Product Line(s): **Certain 2012-2017 ACE, Citation, Four Winds, and Siesta Motorhomes**

Service Campaign # : **RC000121**

Released Date: **8.8.2016**

Failure Code: **TMCRC80452V**

Document Date: **8.8.2016**

Time Allowed: **0.3 hr**

Document Revision: **A**

IDENTIFY "FASTENERS"



Identify 4ea. 'quarter-turn' fasteners on the top
Identify 4ea. 'quarter-turn' fasteners on the bottom

STEP 1



Rotate each fastener 1/4 turn to the left
to disengage curtain from 'guide clips' in the track

STEP 2



Remove the curtain by easily sliding 'upward'

IDENTIFY "CURTAIN BOTTOM"



The 'bottom' of the curtain contains a 2" sewn
stiffener to the 'INSIDE' of the curtain

STEP 3



- Slide new curtain into the channels; left and right
(starting with the 'bottom'- as shown)
- Replace the 8ea. 'quarter-turn' fasteners
(included if needed)