

[Next Unread Message](#)**View Message**

Sent on	09	02	2016	Expires on	11	30	2016
----------------	----	----	------	-------------------	----	----	------

From	Campaign Administration
-------------	-------------------------

Subject	Stop Sale/Safety Recall: 2015 TLX V6 A/T Sensor Cluster Terminal Crimp Failure
----------------	--

DATE: September 2, 2016

TO: All Acura Sales, Service & Parts Managers and Personnel

FROM: Campaign Administration

Re: Stop Sale/Safety Recall: 2015 TLX V6 A/T Sensor Cluster Terminal Crimp Failure

On September 1, 2016, Acura notified NHTSA of a **Stop Sale** order and **Safety Recall** for **certain** model year 2015 Acura TLX V6 vehicles with the 9 speed automatic transmission. Any affected new, used, demo or loaner vehicle in dealer stock must be repaired prior to sale. We are not able to provide a list of those VINs affected through an **eResponsibility report** until September 3, 2016, but you can rely on a **VIN Status Inquiry** search in relation to this action starting September 2, 2016. We will provide an update when more specific information, including the repair information becomes available.

Note: Some vehicles affected by this campaign may be in your used vehicle inventory. Failure to repair a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the client or anyone else harmed as a result of such failure. In addition, state law may provide Acura with the right to seek indemnification in any such claim or lawsuit.

Click [here](#) for a copy of service bulletin 16-075.