



# Service Information

Audio, Navigation, Monitors,  
Alarms, SRS

B65 22 16

Page 1 of 1

September 2016

Technical Service

---

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

## **RECALL CAMPAIGN 16V-XXX: DRIVER'S AIR BAG MODULE F15 F25 F26**

### **MODEL**

|          |          |          |
|----------|----------|----------|
| F15 (X5) | F25 (X3) | F26 (X4) |
|----------|----------|----------|

### **SITUATION**

BMW AG is conducting a Voluntary Safety Recall involving certain Model Year 2014 - 2015 vehicles. This involves the replacement of the driver's air bag module. Due to a supplier production error, inflators were incorrectly welded. This issue is related to supplier production and not propellant.

There are approximately 3,606 vehicles affected by this recall.

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.