

November 2016 Technical Service

RECALL CAMPAIGN 16V-XXX: REPLACE SENSOR CLUSTER UNIT

MODEL

F10 (5 Series Sedan)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving certain Model Year 2011 vehicles. This involves the Sensor Cluster Unit (SCU) that may have been incorrectly programmed by the supplier, entered the spare parts supply chain, and has been installed in a vehicle at dealers during a repair event.

Approximately 91 vehicles are affected by this recall.

This bulletin will be updated with Q & A, repair instructions, parts and warranty information when it becomes available.

ATTACHMENTS

View PDF attachment Recall Notice B652816.

[Copyright ©2016 BMW of North America, Inc.]

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall Campaign 16V-XXX: Replace Electronic Control Unit for Air Bag – Prior Parts Replacement B65 28 16

BMW Group is conducting a Voluntary Safety Recall (effective November 14, 2016) involving the Electronic Control Unit for Air Bag in certain F10 (5 Series Sedan).

Owners will be notified by First Class mail about the Recall and will be instructed to bring their vehicles in for a free repair when parts are available.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.