

## IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-1606** NHTSA RECALL NO. 16V-855 **TC RECALL NO. 2016-600** January, 2017

TO: U.S. and Canadian Distributors Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act.

Autocar, LLC, has decided that a defect that relates to motor vehicle safety exists in 2013-2017 model year Xpeditor chassis. These chassis were manufactured between 10 December 2012 and 1 November 2016 with non-sequential serial numbers in the range 215731 to 223684. Accordingly, a recall to address this issue is being initiated effective 20 January 2017.

Autocar Xpeditor MY 2013-2017 **MODELS** 

AFFECTED:

**COMPONENTS** Ignition relay in the back of cab fuse box.

AFFECTED:

SAFETY DEFECTS The ignition relay coil can open due to vibration of the fuse box. If the ignition relay coil

AND POTENTIAL opens, the engine may stall and fail to restart, increasing the risk of a crash. RISKS:

**REPAIR** An additional bracket will be installed to lower vibration to the fuse box. A Safety Recall REQUIRED: Bulletin with the repair procedure and labor code will be available on 20 January 2017.

**REPAIR** VIN profiles in the Autocar Warranty System will be updated to show the open recall on 20 January 2017. **AVAILABLE:** 

It is a violation of Federal law to sell or lease a vehicle covered by this recall notice REMINDER: unless the recall remedy has been completed. Substantial civil penalties apply to

violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department

at warranty@autocartruck.com.

Sincerely,

**AUTOCAR, LLC** 

ACF 00002 Rev. 000