

I-16-03 DEALER EMAIL

BODY

Dear Indian Motorcycle Dealer,

Indian Motorcycle has made a small but important change to Safety Bulletin I-16-03. During inspection, the **Fuel Line Connector** is the only component that should not contact the fuel tank. The fuel line touching the fuel tank does not quantify the replacement of the fuel rail. Please read the updated [Limiter Bracket Installation](#) procedure in the bulletin for more details.

- [Safety Bulletin I-16-03](#)

Thank you for your attention.

Sincerely,
Polaris Service