

[Next Unread Message](#)

View Message

Sent on 01 10 2017 **Expires on** 01 24 2017

From Parts and Service Division

Subject Incorrect Part Number for Service Bulletin 16-093

Message PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Vehicle Engineering
RE: Incorrect Part Number for Sub-cord Repair Kit in Service Bulletin 16-093

This message is solely directed to Honda dealership personnel; please handle accordingly. Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

On January 7, 2017, an iN message was released regarding Service Bulletin 16-093. The Honda Service Bulletin (16-093 - Safety Recall: Rear Wire Harness/Rear Subframe Harness) lists the part number for the Sub-cord Repair Kit for repair procedure A as 32108-T6Z-301. This is incorrect. The correct part number is 32108-T6Z-306. An updated copy of the service bulletin will be posted soon.

Thank you.