



\_\_\_\_

01/18/2017

## **New Safety Recall Advanced Communication – S96011817**

FCA US LLC ("FCA US") announced a safety recall on certain 2017 model year (VM) RAM ProMaster City vehicles.

Some of the above vehicles were manufactured with improperly manufactured airbag inflator initiators that may not ignite when a deployment voltage is provided to the initiator. As a result, vehicles may experience a "non-deployment" of the seat mounted side airbag ("SAB") during a crash event warranting an airbag deployment. A SAB "non-deployment" when a deployment is warranted may result in reduced occupant restraint, injury or death.

FCA US will conduct a voluntary safety recall to replace the left side seat airbag.

VINs identified as being involved in this campaign are currently live and searchable under Recall S96.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past. Remedy communication is estimated to be available in the first quarter of 2017.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations FCA US LLC