



SAFETY RECALL J081

SERVICE ALERT

24-FEB-17

NO.: JA17RE-01

SEC.: RECALL

MKT.: CAN / USA

Please be advised that the Technical Bulletin relating to SAFETY RECALL J081, *Autoliv Front Seatbelt Pre-Tensioner Operation*, was updated 21 February 2017, with revised affected vehicles and seatbelt inspection procedures.

Retailers' attention is drawn to the following main changes:

- **XE (X760)** - it has been determined that these vehicles are no longer affected and have been removed from the Recall. Any vehicles previously inspected and held may be released for sale.
Claims for the initial inspection may be submitted as described in the Warranty section of the bulletin. Prior to submitting these claims, please submit an email to jlrcamp@jaguarlandrover.com requesting the VIN to be reinstated to allow for claims processing.
- **F-TYPE (X152)** - a new seatbelt production date, code 20.07.16, has been added and requires the re-inspection of seatbelts for all affected VINs.
All previously closed VINs have been reopened in the Recall program and will flag as 'open' in DDW. Please follow the bulletin instructions to re-inspect seatbelts.
Seatbelt production part numbers have also been added to the Inspection Procedure. This may result in vehicles that previously did not pass the Inspection Procedure now passing. All vehicles that do not pass this updated Inspection Procedure must continue to be HELD until publication of an updated Technical Bulletin, with complete parts and repair information, is published. This is currently expected to be available the week of 27 February 2017.

Please refer to the Technical Bulletin **J081NAS3** on TOPIx for further information.