



A **PACCAR** COMPANY

**Kenworth Truck Company**  
P.O. Box 1000  
Kirkland, Washington 98083-1000  
(425) 828-5000

July 13, 2016

## **IMPORTANT SAFETY RECALL**

**Subject:** Safety Recall 16KWA – ICON 900 Headlamps  
NHTSA Recall number 16V-362  
This notice applies to your vehicle; VIN: [REDACTED]



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that certain model year 2016 W900 vehicles manufactured from 05/19/2015 through 12/21/2015 fail to conform to Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". When the headlamps are switched from low beam to high beam there is a chance, due to a circuit overload, that the high beams may be delayed in activation, leaving the headlamps off. Low beam functionality remains available to the operator but requires switching back to low beams.

Unexpected loss of forward lighting may increase the risk of crash.

<b>The problem is...</b>	Unexpected loss of forward lighting
<b>What your dealer will do...</b>	Modify the headlamp wiring harness to prevent the circuit overload
<b>What you must do ...</b>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to modify the headlamp wiring harness. This repair should take approximately **1.0 hour** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at [www.Kenworth.com](http://www.Kenworth.com). If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this noncompliance in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We appreciate your cooperation in this matter.

Sincerely,

Jacob Montero  
Director of After Sales  
Kenworth Truck Company



A **PACCAR** COMPANY

**Kenworth Truck Company**  
P.O. Box 1000  
Kirkland, Washington 98083-1000  
(425) 828-5000

July 13, 2016

## **IMPORTANT SAFETY RECALL**

**Subject:** Safety Recall 16KWA – ICON 900 Headlamps  
NHTSA Recall number 16V-362  
This notice applies to your vehicle; VIN: 1XKWD49XXGJ103313



Kenworth Sales Company - Jerome  
PO Box 379  
Jerome, ID 83338-0379



Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that certain model year 2016 W900 vehicles manufactured from 05/19/2015 through 12/21/2015 fail to conform to Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". When the headlamps are switched from low beam to high beam there is a chance, due to a circuit overload, that the high beams may be delayed in activation, leaving the headlamps off. Low beam functionality remains available to the operator but requires switching back to low beams.

Unexpected loss of forward lighting may increase the risk of crash.

<b>The problem is...</b>	Unexpected loss of forward lighting
<b>What your dealer will do...</b>	Modify the headlamp wiring harness to prevent the circuit overload
<b>What you must do ...</b>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to modify the headlamp wiring harness. This repair should take approximately **1.0 hour** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at [www.Kenworth.com](http://www.Kenworth.com). If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this noncompliance in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We appreciate your cooperation in this matter.

Sincerely,

Jacob Montero  
Director of After Sales  
Kenworth Truck Company



A **PACCAR** COMPANY


**Kenworth Truck Company**  
P.O. Box 1000  
Kirkland, Washington 98083-1000  
(425) 828-5000

July 13, 2016

## **IMPORTANT SAFETY RECALL**

**Subject:** Safety Recall 16KWA – ICON 900 Headlamps  
NHTSA Recall number 16V-362  
This notice applies to your vehicle; VIN: 1XKWD49X5GJ102716



Kenworth Sales Company - Salt Lake City  
2125 S Constitution Blvd  
West Valley City, UT 84119-1219  


Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that certain model year 2016 W900 vehicles manufactured from 05/19/2015 through 12/21/2015 fail to conform to Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". When the headlamps are switched from low beam to high beam there is a chance, due to a circuit overload, that the high beams may be delayed in activation, leaving the headlamps off. Low beam functionality remains available to the operator but requires switching back to low beams.

Unexpected loss of forward lighting may increase the risk of crash.

<b>The problem is...</b>	Unexpected loss of forward lighting
<b>What your dealer will do...</b>	Modify the headlamp wiring harness to prevent the circuit overload
<b>What you must do ...</b>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to modify the headlamp wiring harness. This repair should take approximately **1.0 hour** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at [www.Kenworth.com](http://www.Kenworth.com). If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this noncompliance in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We appreciate your cooperation in this matter.

Sincerely,

Jacob Montero  
Director of After Sales  
Kenworth Truck Company



A **PACCAR** COMPANY


**Kenworth Truck Company**  
P.O. Box 1000  
Kirkland, Washington 98083-1000  
(425) 828-5000

July 13, 2016

## **IMPORTANT SAFETY RECALL**

**Subject:** Safety Recall 16KWA – ICON 900 Headlamps  
NHTSA Recall number 16V-362  
This notice applies to your vehicle; VIN: 1XKWD49X2GJ111907



Kenworth Northwest - Lakewood  
12507 Pacific Hwy SW  
Lakewood, WA 98499-1024  


Dear Kenworth Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company has decided that certain model year 2016 W900 vehicles manufactured from 05/19/2015 through 12/21/2015 fail to conform to Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". When the headlamps are switched from low beam to high beam there is a chance, due to a circuit overload, that the high beams may be delayed in activation, leaving the headlamps off. Low beam functionality remains available to the operator but requires switching back to low beams.

Unexpected loss of forward lighting may increase the risk of crash.

<b>The problem is...</b>	Unexpected loss of forward lighting
<b>What your dealer will do...</b>	Modify the headlamp wiring harness to prevent the circuit overload
<b>What you must do ...</b>	Contact your Kenworth Dealer to schedule an appointment for repair

Kenworth has initiated a recall to modify the headlamp wiring harness. This repair should take approximately **1.0 hour** and will be performed at no charge to you. Please contact your Kenworth dealer immediately to schedule an appointment for this repair. To find your nearest Kenworth dealer, please visit Dealer Locator at [www.Kenworth.com](http://www.Kenworth.com). If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Quality Services Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this noncompliance in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We appreciate your cooperation in this matter.

Sincerely,

Jacob Montero  
Director of After Sales  
Kenworth Truck Company