



This Service Information bulletin supersedes SI B65 04 16 **dated February 2016.**

NEW designates changes to this revision

SUBJECT

Recall Campaign 16V-071: Driver-Side Front Air Bag Module

MODEL

E70 (X5 incl M)

E71 (X6 incl M)

E72 (X6 ActiveHybrid)

E90 (3 Series Sedan incl M)

E91 (3 Series Sportswagon)

E92 (3 Series Coupe incl M)

E93 (3 Series Convertible, incl M)

E82 (1 Series coupe)

E83 (X3)

E84 (X1)

E88 (1 Series convertible)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving Driver-Side Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated Takata PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls.

This is an industry-wide safety recall involving driver's front air bag modules. BMW is committed to helping you manage this recall campaign in the least disruptive fashion.

Affected vehicles, which require this Recall, have been identified and are displayed under **“Open Campaign and Vehicle Comments”** in Warranty Vehicle Inquiry or ISPA Light.

Going forward, all VINs will be shown in the “open campaign” portion of the Warranty Vehicle Inquiry screen below. This enables Service Advisors to see at one glance all applicable Campaigns

and Recalls. Defect code 0000001100 will be used until repair information is released. At that time, the defect code will be updated in the Warranty Vehicle Inquiry screen. Please note, defect code 0000001100 is not an operation defect code and cannot be used on warranty claims. In addition, the information will keep being displayed in the comment section as previously done.

NEW

Open Campaign Information	
Campaign Code	Campaign Description
0000001100	Recall 16V-071 Driver Front Air Bag B650

GRUSB6516-01

NEW All affected customers of this Recall will be mailed an interim letter starting on March 16, 2016. The letter will inform them that their vehicle is included in the recall. A final letter will be mailed to the customers when parts become available. A copy of the letter that was sent to these customers is attached.

We are working diligently to secure a parts solution and will provide you with more details as they develop; a specific date is not available. We will provide you with information regarding the repair process as soon as possible.

To assist you with challenging concerns, please reference the attached Q&A that will be updated as information becomes available. We will continually update the Q&A and you can identify the latest version by the date that is referenced at the bottom of the pages.

We sincerely apologize for any inconvenience this recall may cause; however, be assured that BMW is determined to uphold a high level of vehicle quality and customer satisfaction.

There are approximately 840,000 vehicles in the US.

Model	Model Year	Approx .Volume	Production Dates
1 Series Coupe (incl. M)	2008 – 2013	32,620	Nov 2007 – Oct 2013
1 Series Convertible	2008 – 2013	28,160	Nov 2007 – Oct 2013
3 Series Sedan (incl. M)	2006 – 2011	132,845	Feb 2005 – Dec 2011
3 Series Sedan (diesel)	2009 – 2011	4,160	Mar 2008 – Aug 2011
3 Series Sports Wagon	2006 – 2012	3,270	Jun 2005 – May 2012
3 Series Coupe (incl. M)	2007 – 2013	129,515	Apr 2006 – Jun 2013
3 Series Convertible (incl. M)	2007 – 2013	99,810	Nov 2006 – Oct 2013
X1 SAV	2013 – 2015	57,290	Feb 2012 – Sep 2014
X3 SAV	2007 – 2010	64,925	Aug 2006 – Aug 2010
X5 SAV (incl. M)	2007 – 2013	214,580	Sep 2006 – Jun 2013
X5 SAV (diesel)	2009 – 2013	35,440	Mar 2008 – Jun 2013
X6 SAV (incl. M)	2008 – 2014	37,000	Jul 2007 – Jun 2014
X6 SAV ActiveHybrid	2010 – 2011	365	Mar 2009 – Sep 2011

ATTACHMENTS

View PDF attachment [B650416 Recall Notice.](#)

View PDF attachment [B650416 Q&A 5.](#)

View PDF attachment [B8 0216 20a Safety Recall 16V071.](#)

View PDF attachment [B650416 Dealer Script Recall.](#)

View PDF attachment [B650416 Interim Customer Letter.](#)

[Copyright ©2016 BMW of North America, Inc.]