



This Service Information bulletin supersedes SI B65 04 16 **dated February 2016.**

SUBJECT

Recall Campaign 16V-071: Driver-Side Front Air Bag Module

MODEL

E70 (X5 incl M)

E71 (X6 incl M)

E72 (X6 ActiveHybrid)

E90 (3 Series Sedan incl M)

E91 (3 Series Sportswagon)

E92 (3 Series Coupe incl M)

E93 (3 Series Convertible, incl M)

E82 (1 Series coupe)

E83 (X3)

E84 (X1)

E88 (1 Series convertible)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving Driver-Side Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated Takata PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls.

BMW Group is participating as part of the industry-wide voluntary safety recall involving driver-side front airbag modules. BMW is committed to helping you manage this recall campaign in the least disruptive fashion.

Affected vehicles, which require this Recall, have been identified and will display under “**vehicle comments**” in DCS Warranty or ISPA Light.

We will provide you with more information regarding the repair process and parts availability as soon as possible. We are working diligently to secure a parts solution and will provide you with more details in the coming week. Thank you for your patience.

To assist you with challenging concerns, please reference the attached Q&A that will be updated as information becomes available. We will continually update the Q&A and you can identify the latest version by the date that is referenced at the bottom of the pages.

NEW In addition, if there are any business operation and sales questions, a **NEW** Q&A is attached and also provided in CenterNet: **NEW** #B8_0216_20a_safety_recall_16V071.

NEW We sincerely apologize for any inconvenience this recall may cause; however, be assured that BMW is determined to uphold a high level of vehicle quality and customer satisfaction.

There are approximately 840,000 vehicles in the US.

| Model | Model Year | Approx .Volume | Production Dates |
|--------------------------------|-------------------|-----------------------|-------------------------|
| 1 Series Coupe (incl. M) | 2008 – 2013 | 32,620 | Nov 2007 – Oct 2013 |
| 1 Series Convertible | 2008 – 2013 | 28,160 | Nov 2007 – Oct 2013 |
| 3 Series Sedan (incl. M) | 2006 – 2011 | 132,845 | Feb 2005 – Dec 2011 |
| 3 Series Sedan (diesel) | 2009 – 2011 | 4,160 | Mar 2008 – Aug 2011 |
| 3 Series Sports Wagon | 2006 – 2012 | 3,270 | Jun 2005 – May 2012 |
| 3 Series Coupe (incl. M) | 2007 – 2013 | 129,515 | Apr 2006 – Jun 2013 |
| 3 Series Convertible (incl. M) | 2007 – 2013 | 99,810 | Nov 2006 – Oct 2013 |
| X1 SAV | 2013 – 2015 | 57,290 | Feb 2012 – Sep 2014 |
| X3 SAV | 2007 – 2010 | 64,925 | Aug 2006 – Aug 2010 |
| X5 SAV (incl. M) | 2007 – 2013 | 214,580 | Sep 2006 – Jun 2013 |
| X5 SAV (diesel) | 2009 – 2013 | 35,440 | Mar 2008 – Jun 2013 |
| X6 SAV (incl. M) | 2008 – 2014 | 37,000 | Jul 2007 – Jun 2014 |
| X6 SAV ActiveHybrid | 2010 – 2011 | 365 | Mar 2009 – Sep 2011 |

ATTACHMENTS

View PDF attachment [B650416 Recall Notice](#).

View PDF attachment [B650416 Q&A 4](#).

View PDF attachment [B8 0216 20a Safety Recall 16V071](#).

[Copyright ©2016 BMW of North America, Inc.]