



Service Bulletin

American Honda Motor Co., Inc.

SAFETY RECALL

2014 NSS300/A REAR BRAKE LINE JOINT TORQUE

(Interim Bulletin, final bulletin will be available by February 26, 2016)

Honda Motor Co., Ltd. is conducting a Safety Recall of all model year 2014 NSS300 and NSS300A (Forza) scooters. Honda has determined that during assembly, the rear brake line joint may have been improperly torqued. If the brake line joint is improperly torqued, brake fluid may leak causing a reduction or loss of rear brake pressure.

Honda dealers will torque the rear brake line joint to specification and, if necessary, fill the rear brake reservoir.

Safety Consequence

A reduction or loss of rear brake pressure increases the risk of a crash.

CUSTOMER NOTIFICATION

During the month of March 2016, Honda will mail a letter to all owners of affected vehicles informing them that their scooter is being recalled for a safety related defect. The customer will be made aware of the safety risk and advised to have a Honda dealer confirm the torque on the affected part.

AFFECTED UNITS

2014 NSS300 All units

2014 NSS300A All units

DEALER INVENTORY

Do not sell any un-repaired units.

According to federal law, any affected units in your new inventory cannot be sold or leased until they are repaired according to the forthcoming repair procedure and Honda policy prohibits the sale of new or used un-repaired units.

To search for applicable recalls on a specific unit, refer to *Unit Information* on **iN**.

To manage your affected inventory, use *eResponsibility Report* on **iN**.