

TECHNICAL BULLETIN

P077NAS2

02 JUN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

Changes are highlighted in gray

SECTION: 417-01

Non-Compliance Recall: Rear License Plate Lamp Loose

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)

Model Year: 2015-2016

VIN: 500429-605785

Assembly Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A non-compliance issue has been identified on vehicles within the Affected Vehicle Range where the rear license plate lamp housing(s) may lose retention within the tailgate finisher and subsequently fall out.

Action: Retailers are required to **HOLD** only affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
License plate lamp	LR087728	2	100

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required tools.

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **P077** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

PROGRAM	OPTION	DESCRIPTION	SRO	TIME	PARTS/SUNDRY	QTY./VALUE
---------	--------	-------------	-----	------	--------------	------------

CODE	CODE			(HOURS)	CODE	
P077	B	License plate lamp - Set - Renew	86.40.92	0.10	LR087728	2
P077	C	License plate lamp - Set - Renew Drive in/drive out	86.40.92 02.02.02	0.10 0.20	LR087728 -	2 -

Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Renew the right-hand and left-hand license plate lamps (see TOPIx Workshop Manual section 417-01: Exterior Lighting - License Plate Lamp).