



Service Bulletin

American Honda Motor Co., Inc.

STOP SALE NOTICE

2015-2016 CBR300R/CB300F CRANKSHAFT REPLACEMENT (Interim bulletin, a revised bulletin will be available late July 2016).

Honda is announcing a STOP SALE NOTICE of model year 2015 through 2016 CBR300R and CB300F motorcycles to repair a potentially defective crankshaft on affected vehicles. If the connecting rod bearing retainer breaks, the engine may stall and/or not restart.

Safety Consequence

An engine that stalls while riding increases the risk of a crash.

AFFECTED UNITS

2015 CBR300R - All
2015 CB300F - All
2016 CBR300R - All
2016 CB300F - All

DEALER INVENTORY UNITS

Effective immediately, YOU MUST NOT SELL any 2015 through 2016 CBR300R and CB300F motorcycle until it has been repaired according to Service Bulletin CBR300R/CB300F #1.

- iN eResponsibility Report will show the affected units in your dealership's inventory.
- To determine if a specific VIN is affected, use iN Unit Information.