



Waterous Company – Since 1886
Subsidiary of American Cast Iron Pipe Company

**NHTSA Recall 16E059
Recall Remedy Instructions**

Waterous is sending the affected OEMs retrofit kits to replace the shift unit's clevis pin and retaining rings with a shoulder bolt and locking nut. Each retrofit kit will be individually packaged and will include detailed installation instructions (see attached). The retrofit kits should then be forwarded by the OEMs to the affected customers.

The recall remedy may be performed by the OEM, the OEM Dealer, an independent repair facility approved by the OEM, or the end user. It is anticipated that the installation of the retrofit kit will take less than one hour per vehicle.

INCLUDED WITH THE RETROFIT KIT INSTRUCTIONS IS A CERTIFICATE OF REMEDY AND DISPOSAL FORM THAT MUST BE FILLED OUT AND RETURNED TO WATEROUS. Upon receipt of each completed Certificate, Waterous will credit the OEM account for \$312 as follows:

2-hours travel time @ \$100/hour	\$200
1-hour repair time @ \$100/hour	\$100
Shipping charge	<u>\$ 12</u>
Total	\$312

Questions regarding this recall remedy should be addressed to:

Waterous Company
Mark Blake
Senior Technical Service Specialist
651.450.5067
mablake@waterousco.com