

September 3, 2016

04850 Version 1

Safety Recall: 2015 TLX V6 A/T Sensor Cluster Crimp Failure

AFFECTED VEHICLES

Year	Model	Trim	VIN range
2015	TLX	V6 with A/T	Check the iN VIN status for eligibility

BACKGROUND

Certain 2015 model year Acura TLX vehicles with A/T could have the TCU (Transmission Control Unit) go into failsafe mode, causing the transmission to shift into neutral. The lack of terminal crimping on the 9A/T harness coupler can cause a resistance in the course of usage. This resistance is detected as a failure by the TCU. The TCU then places the transmission into neutral "N", failsafe mode to protect the transmission.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.