



Service Bulletin

American Honda Motor Co., Inc.

SAFETY and EMISSIONS RECALL

2014-2015 Grom125 FUEL PUMP REPLACEMENT

(Interim bulletin, a revised bulletin will be available September 23, 2016).

Honda Motor Co., Ltd. is conducting a Safety and Emissions Recall of affected 2014-2015 Grom125 motorcycles. Honda has determined that a defect within the fuel pump can cause the pump to seize, resulting in a loss of fuel pressure. Loss of fuel pressure will cause the engine to A) not start or B) stall while riding.

Replacement fuel pumps are available to correct this condition.

Safety Consequence

An engine that stalls while riding increases the risk of a crash.

CUSTOMER NOTIFICATION

In early October, 2016 American Honda will send a letter to owners of all affected 2014-2015 Grom125 motorcycles, informing them that their motorcycle is being recalled for a safety and emissions related defect. The customer will be made aware of the safety risk and advised to have a Honda dealer replace the fuel pump.

AFFECTED UNITS

2014 and 2015 Grom125

Certain VINs

DEALER INVENTORY

Effective September 12, 2016 YOU MUST NOT SELL any affected NEW or USED 2014-2015 Grom125 motorcycle until it has been repaired according to Service Bulletin Grom125 #1.

- **iN eResponsibility Report** will show the affected units in your dealership's inventory.
- To determine if a specific VIN is affected, use **iN Unit Information**.