

# Thor Motor Coach Recall Repair Instructions



Recall # 16V—834  
Description/Title: **Tuscany Keyless Entry Module Short**

Affected Product Line(s): **Certain Tuscany Motorhomes**

Service Campaign # : **RC000123** Released Date: **1.9.17**

Failure Code: **TMCRC80454V** Document Date: **1.9.17**

Time Allowed: **0.2** Document Revision: **A**

## Items needed: 1 can expanding spray foam to be procured locally.

Please note : To avoid delays in claim processing, be sure to attach a copy of the receipt or invoice from your purchase of the spray foam to the warranty claim. Thor Motor Coach will reimburse the cost of the spray foam up to \$5.00

## Instructions:

1. From the outside of the motorhome open the electronics' bay compartment door. This will be the first compartment door on the driver's side of the motor home.
2. Locate the opening at the top right hand corner of the rearmost compartment wall.
3. Clean the area surrounding the opening to remove any moisture, oil, or debris.



4. Fill the opening with expanding spray foam.
5. Clean the area of any drips or other areas of stray spray foam.

