

Replacement of Spare Tire steel Wheel with Aluminum Wheel of Landmark w/Disc Brakes

Description

On certain Landmark fifth wheel trailers manufactured with the Disc Brake Option, The spare tire steel wheel will not correctly fit on the axle hub with units that have the disc brake option. The steel wheel will not seat correctly requiring constant re-torque and will rub against the disc brake caliper till it comes into contact with the brake line. The correction is to replace the WHEEL of the spare tire with an aluminum wheel.

Inspection & Repair

Identify the ladder bracket

1. Remove lock pin and unbolt spare tire hanger, drop and pull mount from under the RV to gain access to tire.
2. Remove the 2 mounting bolts from the frame and remove spare tire.
3. Have the tire remounted to the aluminum rim.
4. Repeat steps 1&2 to reinstall the spare tire on the carrier.

Parts

Aluminum Rim # 0251650

Warranty

File Recall Repair warranty claim using warranty code 99.01.30. B for 0.20 hours. Plus the sublet cost.

Please refer all questions and authorization requests to Heartland Dealer Services Department 877-262-8032