

IMPORTANT: SAFETY RECALL REMINDER

In November 2016, we notified you of a Safety Recall involving the Airbag Module on your 2006 – 2010 GL1800 motorcycle. At the time, we advised owners of the following:

Honda has decided that a defect that relates to motor vehicle safety exists in certain 2006-2010 model year Gold Wing GL1800 motorcycles equipped with an airbag. The propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the airbag is activated. Overly-aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material possibly causing a serious or fatal injury to the rider or passenger.

According to our records, you have not yet had your affected motorcycle repaired. Please call your authorized Honda Motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If your motorcycle has already been repaired, or if you no longer own this motorcycle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda Motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.
Motorcycle Division**