



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BAB5236FF0D1449, 10BAB5232FF0D1450, 10BAB5234FF0D1451, 10BAB5236FF0D1452,
10BAB5238FF0D1453, 10BAB523XFF0D1454, 10BAB5231FF0D1455

Transport Service Co.
2001 Spring Road Suite 400
Oakbrook, IL. 60523

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer. *Note: this issue presents no impact on the tractor brakes.*

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should ***always use*** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: ***do not*** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>


If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BAB6230GF0D3608, 10BAB6232GF0D3609, 10BAB6239GF0D3610, 10BAB6230GF0D3611
10BAB6232GF0D3612, 10BAB6234GF0D3613, 10BAB6236GF0D3614, 10BAB6238GF0D3615

Ryder Transportation Services (GA)
1499 Lissner Ave.
Savannah, GA. 31408
Address

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer. *Note: this issue presents no impact on the tractor brakes.*

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should ***always use*** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: ***do not*** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BFB5232FF0D2183, 10BFB5234FF0D2184, 10BFB5236FF0D2185, 10BFB5238FF0D2186,
10BFB5233FF0D2189, 10BFB5231FF0D2224, 10BFB5233FF0D2225, 10BFB7238FF0D2555,
10BFB723XFF0D2556, 10BFB7231FF0D2557, 10BFB7233FF0D2558, 10BFB7235FF0D2559,
10BFB723XGF0D2560, 10BFB7231GF0D2561, 10BFB4237FF0D2562, 10BFB4239FF0D2563,
10BFB4230FF0D2564, 10BFB4232FF0D2565, 10BFB5230GF0D2748, 10BFB5232GF0D3156,
10BFB5234GF0D3157, 10BFB5236GF0D3158, 10BFB5238GF0D3159, 10BFB5231GF0D3438,
10BFB5233GF0D3439, 10BFB523XGF0D3440, 10BFB5238GF0D3842, 10BFB523XGF0D3843,
10BFB5231GF0D3844, 10BGB5230GF0D3872, 10BFB7232GF0D4030, 10BFB7239GF0D4090,
10BFB7232GF0D4092, 10BFB7234GF0D4093, 10BFB7236GF0D4094, 10BFB7238GF0D4095,
10BFB723XGF0D4096, 10BFB7231GF0D4097, 10BFB7233GF0D4098, 10BFB7235GF0D4149,
10BFB7231GF0D4150, 10BFB7233GF0D4151, 10BFB7235GF0D4152, 10BFB7231GF0D4293,
10BFB7233GF0D4294

Dana Transport
210 Essex Avenue
Avenel, NJ. 07001

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer. *Note: this issue presents no impact on the tractor brakes.*

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should **always use** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: **do not** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BFB723XFFOD1777, 10BFB7231FFOD1778, 10BFB7233FFOD1779, 10BFB723XFFOD1780
10BFB7231FFOD1781, 10BFB723XGFOD3076, 10BFB7231GFOD3077, 10BFB7233GFOD3078,
10BFB7235GFOD3079, 10BFB7231GFOD3080

Tidewater Transit Co. Inc.
PO Box 189
Kinston, NC. 28502

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer.
Note: this issue presents no impact on the tractor brakes.

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should ***always use*** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: ***do not*** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BFB723XFFOD1777, 10BFB7231FFOD1778, 10BFB7233FFOD1779, 10BFB723XFFOD1780
10BFB7231FFOD1781, 10BFB723XGFOD3076, 10BFB7231GFOD3077, 10BFB7233GFOD3078,
10BFB7235GFOD3079, 10BFB7231GFOD3080

Tidewater Transit Co. Inc.
PO Box 189
Kinston, NC. 28502

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer.
Note: this issue presents no impact on the tractor brakes.

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should ***always use*** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: ***do not*** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>


If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:

10BFB7234FF0D1435, 10BFB7236FF0D1436, 10BFB7238FF0D1437

Tankmart International
4545 Ave. DES Industries
Laval, Quebec H7C1A1

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer. *Note: this issue presents no impact on the tractor brakes.*

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should **always use** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: **do not** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>


If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicle:
10BEA742XGP003299

Weaver Bros., Inc.
2230 Spar Avenue
Anchorage, AK. 99501

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer.
Note: this issue presents no impact on the tractor brakes.

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should **always use** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: **do not** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicles:

10BFB7236FFOD1999, 10BFB7232FFOD2566, 10BFB7234FFOD2567, 10BFB7236FFOD2568,
10BFB7238FFOD2569, 10BFB7234FFOD2570, 10BFB7236FFOD2571, 10BFB7238FFOD2572,
10BFB723XFFOD2573, 10BFB7231FFOD2574, 10BFB6230FFOD2575, 10BFB6232FFOD2576,
10BFB6234FFOD2577, 10BFB7238GFOD3237, 10BFB723XGFOD3238, 10BFB7231GFOD3239
10BFB7238GFOD3240, 10BFB723XGFOD3241, 10BFB7231GFOD3242, 10BFB7233GFOD3243
10BFB7235GFOD3244, 10BFB7237GFOD3245, 10BFB7239GFOD3246, 10BFB7230GFOD3247,
10BFB7232GFOD3248, 10BFB723XGFOD4065, 10BFB7231GFOD4066, 10BFB7233GFOD4067
10BFB7235GFOD4068, 10BFB7237GFOD4069, 10BFB7233GFOD4070, 10BFB7235GFOD4071
10BFB7237GFOD4072, 10BFB7239GFOD4073, 10BFB7239HFOD4561

Mils, Inc.
5500 Hwy 80 West
Jackson, MS 39215-1123

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer.
Note: this issue presents no impact on the tractor brakes.

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

450 Arlington Ave.

Fond du Lac, WI 54935

Phone: 920-322-1041

- When parking, drivers should **always use** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: **do not** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>


If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935



August 22, 2016

**IMPORTANT SAFETY RECALL
INTERIM NOTICE
NHTSA Recall# 16V-489**

This notice applies to your vehicles:

10BGB6236FFOD1421, 10BGB6238FFOD1422, 10BGB623XFFOD1423, 10BGB6231FFOD1424,
10BFB7231FFOD1652, 10BFB7233FFOD1653, 10BFB7235FFOD1654, 10BFB7237FFOD1655,
10BFB7239FFOD1656, 10BFB7230FFOD1657, 10BFB7232FFOD1658, 10BFB7234FFOD1659,
10BFB7230FFOD1660, 10BFB7232FFOD1661, 10BFB7234FFOD1662, 10BFB7236FFOD1663,
10BFB7238FFOD1664, 10BFB723XFFOD1665, 10BFB7231FFOD1666, 10BFB7233FFOD1667,
10BFB7235FFOD1668, 10BFB7237FFOD1669, 10BFB7234GFOD3249, 10BFB7230GFOD3250
10BFB7232GFOD3251, 10BFB7234GFOD3252, 10BFB7236GFOD3253, 10BFB7238GFOD3254
10BFB723XGFOD3255, 10BFB7231GFOD3256 & 10BFB7230HFOD4576

Miller Transporters Inc.
PO Box 1123
Jackson, MS 39215-1123

Dear Brenner Tank Customer,

This Interim notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Brenner Tank has decided that a defect which relates to motor vehicle safety exists in certain WNC trailers equipped with Bendix Commercial Vehicle Systems (Bendix) SR-5 spring brake valves manufactured between January 1, 2014 and March 4, 2016. This decision was based upon information provided by to us by Bendix in their recall 16E045.

A complete listing of trailers impacted by this recall is included with this letter.

Description of Defect:

Under a combination of a unique set of circumstances, it is possible for an internal leakage to develop in the SR-5 unit, resulting in slow to apply spring brakes when parking the trailer. If there is a leak, it may be heard or observed at the supply (red) gladhand when uncoupled from the tractor. If coupled to a tractor, a leak may be heard from the exhaust of the park control valve (Bendix® MV-3™ dash control valve) or from the tractor protection valve.

If uncoupled, and the internal leakage presents itself, loss of air pressure in the trailer reservoir will result. If a high rate of leakage is observed from the supply gladhand or park control valve exhaust (as noted above), it is possible that the spring brakes will be slow to apply on the trailer. *Note: this issue presents no impact on the tractor brakes.*

Risk to Motor Vehicle Safety:

If there is a delay of the spring brake application, the trailer may roll away after it has decoupled from the tractor, increasing the risk of a crash or injury.

Precautions You Should Take:

The following actions can be taken by vehicle owners until the final remedy is available:

- When parking, drivers should ***always use*** the yellow "PARKING BRAKE" button to assure both the tractor and trailer (including yard tractors) are parked: ***do not*** park your vehicle using only the red "TRAILER AIR SUPPLY" button.
- **SPECIAL NOTE FOR IN-YARD MANEUVERING:** Park vehicle on level surfaces, lower the fifth wheel and ensure the landing gear is in contact with the ground prior to pulling away. As an additional precaution, wheel chocks are recommended.

Remedy:

This is the first of two notices that you will receive concerning this matter. A remedy is currently being finalized by Bendix. While Bendix will be administrating this recall directly, you will be notified by both Bendix and WNC, what additional actions you should take, once those details become available.

Further Assistance:

If you have additional questions at this time regarding this recall, feel free to contact the Wabash National Warranty Department at 765-771-5404, Monday – Friday, 8:00am – 5:00pm, ET. You may also contact the Bendix Recall Assistance Center at 877-345-9526, Monday – Friday, 8:00am – 5:00pm, ET, or email at <SR5campaign@bendix.com>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within 10 days to comply with federal regulations.

Complaints:

You may also submit complaints to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C. 20590 or call the toll-free vehicle safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>, if it is believed that the defect has not been remedied without charge or within a reasonable time.

We apologize for the inconvenience caused by this safety recall.

Thank you,



Rick Kostro
Quality / Warranty Assistant Manager
Brenner Tank
450 Arlington Ave.
Fond du Lac, WI 54935