





Recall Campaign 16V-071: Driver's Front Air Bag Module

New information provided by this revision is preceded by this symbol .

This Service Information bulletin supersedes SI B65 04 16 **dated March 2016**.

 SI B65 04 16 was divided into several SIB's, one for each model or group of models. This grouping was done on the basis of vehicles that use the same air bag.

MODEL

E70 (X5 incl M) E71 (X6 incl M) E72 (X6 ActiveHybrid) E84 (X1) See SI B65 14 16	E83 (X3) See SI B65 15 16 to be released soon pending parts availability	E82 (1 Series Coupe) E88 (1 Series Convertible) E90 (3 Series Sedan) E91 (3 Series Sports Wagon) E92 (3 Series Coupe) E93 (3 Series Convertible) See SI B65 16 16 to be released soon pending parts availability
--	--	---

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving Driver's Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated Takata PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls.

This is an industry-wide safety recall involving driver's front air bag modules. BMW is committed to helping you manage this recall campaign in the least disruptive fashion.

 Please reference the correct bulletin number listed above for your vehicle.

[Copyright ©2016 BMW of North America, Inc.]