

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop: F25 F26 ISOFIX Bracket
Date: Friday, May 13, 2016 4:03:36 PM

Publish Date: May 13, 2016
From: Technical Service
Expiration Date: May 27, 2016

DCSnet Message
Urgent



Subject: **Delivery Stop: F25 F26 ISOFIX Bracket**

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

BMW AG has issued a Delivery Stop for F25 (X3) and F26 (X4) vehicles, which require a rework of the ISOFIX bracket. At this time, a repair solution is being developed. You will be updated when information becomes available.

Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the delivery stop repair has been performed. This means that centers may not legally deliver new motor vehicles to a consumer until it is fixed or use/sell replacement equipment/parts subject to a delivery stop. Note also that substantial civil penalties apply to violations of this law.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a delivery stop until the repair is completed.

Sincerely

Technical Service

Merita Fitzgibbon

Attachments: [B410116_Delivery_Stop_Legal\[817146a5\].pdf](#)
 [B410116\[817146a4\].pdf](#)
 [B410116_Delivery_Stop_Legal\[817146a5\].pdf](#)
 [B410116\[817146a4\].pdf](#)

Recipients: BMW Passenger Cars, Service, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, Part Sales, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, New Vehicle Sales, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, All Offerings, All Regions, All Areas, Operations, General Manager



SUBJECT

Delivery Stop – ISOFIX Bracket

MODEL

F25 (X3)

F26 (X4)

SITUATION

A Delivery Stop has been issued on the F25 produced from December 2010 to April 15, 2016 and F26 vehicles produced from April 2014 to April 15, 2016. There is a potential for the ISOFIX (also known as LATCH- Lower Anchors and Tethers for Children) bracket to break while in use. These vehicles will require a rework to be performed.

This bulletin will be updated with repair instructions and warranty information when they become available.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

“A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. Refer to Service Information Bulletin B41 01 16.”

Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the delivery stop repair has been performed. This means that centers may not legally deliver new motor vehicles to a consumer until it is fixed or use/sell replacement equipment/parts subject to a delivery stop. Note also that substantial civil penalties apply to violations of this law.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a delivery stop until the repair is completed.