

DAIMLER

If applicable, identify the manufacture of the defective or noncompliant component.

Supplier:

Ricon Corporation, A Wabtec Subsidiary
1135 Aviation Place
San Fernando, CA 91340

Chronology of Defect / Noncompliance Determination

Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision.

Date	Fact of Event
March 2016	Ricon submits 573 to NHTSA regarding a population expansion to recall 15E-068.
July 2016	DTNA Compliance became aware of the potential recall.
July 2016 through August 2016	DTNA investigated the issue.
August 2016	DTNA decided to initiate voluntary recall campaign.

Identify the Remedy

Describe the defect/noncompliance remedy program, including the manufacture's plan for reimbursement.

DTNA will notify owners and Ricon dealers will perform the repair. Please see Ricon Defect Information Report for 16E-020 which states "The remedy program consists of inspection and replacement: 1) inspect the link arms for damage, and check if the bearings have moved out of position for any reason. 2) Inspect the platform for any signs of cracking or failure. If damage to the link arm or the platform exists, replacement link arms and/or platform will be supplied at no cost."

Identify the Recall Schedule

Describe the recall schedule for notifications.

Customer notification will be made by first class mail using Daimler Truck North America records to determine the customers affected.

Planned Dealer Notification Begin Date:	10/27/2016
Planned Dealer Notification End Date:	10/27/2016
Planned Owner Notification Begin Date:	10/27/2016
Planned Owner Notification End Date:	10/27/2016

Manufacture's identification code for this recall (if applicable): FL-716

DTNA Representative;



Andy Jones
Manager
Compliance and Regulatory Affairs