

Safety Recalls P095 / J081 – Front Seat Belt Pre-tensioner



- Supplier Quality issue - pre-tensioner may not activate when required due to chemical mix spec. error. Parts not traced to VIN. c 15% of vehicle build range may contain defective parts.
- 13,500 US and 1,459 Canadian RR/RRS/Discovery Sport
- 8,232 USA and 555 Canadian F-TYPE and XE.
- Dec 28th 2016 - Recalls announced with inspection procedure tied to belt date code. New units passing inspection may be sold and delivered. Units failing inspection must be held pending publications of Recall repair.
- Improved supplier data linking model/belt part number and date code has recently resulted some changes to affected population.
- Additional date code identified for F-TYPE - may result in some inspected vehicles being re-opened for 2nd inspection. Also for both recalls, some units that failed inspection may now pass.
- Revised bulletins with updated inspection information and claim instructions due by Feb 13th
- Replacement parts and Recall repair launch due by Feb 24th