



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 1, 2017

Mr. Nathan Boyd
Director, Product Integrity
Harley-Davidson Motor Company
11800 W. Capitol Drive
Wauwatosa, WI 53222

NEF-150TB
17V-333

Subject: Engine Oil Cooler Line Clamp Incorrectly Installed

Dear Mr. Boyd:

This letter serves to acknowledge Harley-Davidson Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HARLEY-DAVIDSON/FLHP/2017
HARLEY-DAVIDSON/FLHR/2017
HARLEY-DAVIDSON/FLHRXS/2017
HARLEY-DAVIDSON/FLHTCU/2017
HARLEY-DAVIDSON/FLHTP/2017
HARLEY-DAVIDSON/FLHX/2017
HARLEY-DAVIDSON/FLHXS/2017
HARLEY-DAVIDSON/FLTRX/2017
HARLEY-DAVIDSON/FLTRXS/2017

Mfr's Report Date: May 22, 2017

NHTSA Campaign Number: 17V-333

Components:

ENGINE AND ENGINE COOLING

Potential Number of Units Affected: 45,589

Problem Description:

Harley-Davidson Motor Company (Harley-Davidson) is recalling certain 2017 Electric Glide Ultra Classic (FLHTCU), Police Electra Glide (FLHTP), Police Road King (FLHP), Road King (FLHR), Road King Special (FLHRXS), Street Glide (FLHX), Street Glide Special (FLHXS), Road Glide (FLTRX), and Road Glide Special (FLTRXS) motorcycles. In the affected motorcycles, a clamp used to secure an engine oil cooler line may have been improperly installed.

Consequence:

The incorrectly installed clamp may result in the engine oil cooler detaching, causing a sudden loss of oil, potentially into the path of the rear tire, increasing the risk of a crash.

Remedy:

Harley-Davidson will notify owners, and dealers will inspect and correct the oil cooler line clamps, as necessary, free of charge. The

recall is expected to begin on June 6, 2017. Owners may contact Harley-Davidson customer service at 1-800-258-2464. Harley-Davidson's number for this recall is 0170.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Harley-Davidson's proposed owner notification letter and have approved it for distribution after some edits.


Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jennifer Timian', with a date '1/1/06' written at the end of the signature.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement