



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 7, 2017

Mr. Steve Johnson
Director, Engineering and Design Analysis
Hyundai Motor America
10550 Talbert Avenue
Fountain Valley, CA 92708

NEF-150TB
17V-359

Subject: Parking Brake Indicator may not illuminate

Dear Mr. Johnson:

This letter serves to acknowledge Hyundai Motor America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/GENESIS/2015-2016
HYUNDAI/SONATA/2015-2016

Mfr's Report Date: June 5, 2017

NHTSA Campaign Number: 17V-359

Components:

PARKING BRAKE:INDICATOR LIGHT

Potential Number of Units Affected: 161,074

Problem Description:

Hyundai Motor America (Hyundai) is recalling certain 2015-2016 Sonata and Genesis vehicles. In the affected vehicles, the warning light to indicate that the parking brake is applied may intermittently not illuminate in the dash due to corrosion in the switch.

Consequence:

If the parking brake indicator is not illuminated when the parking brake is applied, the driver may operate the vehicle with the parking brake partially engaged, increasing the risk of a crash.

Remedy:

Hyundai will notify owners, and dealers will replace the parking brake switch, free of charge. The recall is expected to begin on June 30, 2017. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 164.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Hyundai's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please amend the 573 to explain why the brake switch was revised and put into production use starting in 2015.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jennifer Timian', with a date '1/21/16' written at the end of the signature.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement