



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 21, 2017

Ms. Helen Riehle
Safety Integrity and Recall Manager
BMW of North America, LLC
300 Chestnut Ridge Road
Woodcliff Lake, NJ 07677

NEF-150SM
17V-377

Subject: Incorrect Engine Cooler Oil Line Installed

Dear Ms. Riehle:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/M760LI/2017-2018

Mfr's Report Date: June 14, 2017

NHTSA Campaign Number: 17V-377

Components:

ENGINE AND ENGINE COOLING

Potential Number of Units Affected: 206

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2017-2018 M760Li xDrive vehicles. The affected vehicles may have had incorrect engine oil cooler line installed, causing an oil leak in the engine compartment.

Consequence:

If oil leaks onto the front brake discs, a greater distance may be needed to stop the vehicle, increasing the risk of a crash.

Remedy:

BMW will notify owners, and dealers will replace the engine oil cooler line, free of charge. The recall is expected to begin August 7, 2017. Owners may contact BMW customer service at 1-800-525-7417. Note: This recall supersedes recall 17V-240.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.


Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jennifer Timian', with a date '10/20' written at the end of the signature.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement