



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 26, 2017

Mr. John Turley
Honda (American Honda Motor Co.)
1919 Torrance Blvd
Torrance, CA 90501

NEF-150SM
17V-805

Subject: Fuel Tank Welds Missing Causing Fuel Leak

Dear Mr. Turley:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/VT1300CX FURY/2010, 2016-2017

Mfr's Report Date: December 13, 2017

NHTSA Campaign Number: 17V-805

Components:

FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

Potential Number of Units Affected: 20

Problem Description:

Honda (American Honda Motor Co.) is recalling certain 2017 Honda VT1300CX Fury motorcycles and 2010 and 2016 Honda VT1300CX Fury motorcycles that received a replacement fuel tank. The fuel tank may be missing welds around the mounting bracket.

Consequence:

If the welds are missing, the mounting bracket can separate from the tank, allowing fuel to leak and increasing the risk of a fire in the presence of an ignition source.

Remedy:

Honda will notify owners, and dealers will inspect the fuel tank welds and, as necessary, replace the fuel tank, free of charge. The recall is expected to begin in December 2017. Owners may contact Honda customer service at 1-888-234-2138.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement