

# Part 573 Safety Recall Report

# 17E-052

**Manufacturer Name :** BMW of North America, LLC

**Submission Date :** AUG 21, 2017

**NHTSA Recall No. :** 17E-052

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** BMW of North America, LLC

**Address :** P.O. Box 1227

Westwood NJ 07675-1227

**Company phone :** 18005257417

## Population :

**Number of potentially involved :** 9,000

**Estimated percentage with defect :** 100 %

## Equipment Information :

**Brand / Trade 1 :** BMW

**Model :** BMW Motorcycle Dealer Accessory Turn Signals

**Part No. :** See Desc Info

**Size :** NR

**Function :** NR

**Descriptive Information :** Approximately 9,000 dealer accessory turn signals (for Model Year 2006 - 2017 BMW R1200GS, Model Year 2007 - 2008 and 2010 - 2017 R1200GS Adventure, Model Year 2017 F700GS, Model Year 2013 - 2017 F800GT, Model Year 2015 - 2016 F800R, Model Year 2017 F800GS, Model Year 2014 - 2017 F800GS Adventure, Model Year 2014 - 2016 S1000R, Model Year 2015 - 2017 R1200R, Model Year 2016 - 2017 R1200RS, and Model Year 2010 - 2017 S1000RR motorcycles), do not conform to FMVSS 108.

**Basis for recall population determination:** Available only as an accessory.

**Recall component differentiation to non-recall component:** Available only as an accessory.

**Part No.:** 7 708 048, 7 710 574, 7 710 575, 7 710 576, 7 714 326, 8 522 499, 8 522 500, 8 522 501, 8 522 502, 8 522 503

**Production Dates :** JAN 01, 2006 - AUG 11, 2017

## Description of Noncompliance :

**Description of the Noncompliance :** This non-compliance involves dealer accessory turn signals which do not conform to FMVSS 108 as they were not designed for the US market.

**FMVSS 1 :** 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : In certain road and traffic conditions, use of the accessory turn signals may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : ZKW Slovakia s.r.o.

Address : Bedzianska Cesta 679/ 375  
Krusovce FOREIGN STATES 95631

Country : Slovakia

## Chronology :

On July 31 2017, BMW first became aware of this issue during a review of a BMW motorcycle project. The issue involved the parts release of the dealer accessory turn signals, and was thought to relate to FMSS 108. An engineering review was initiated.

Between July 31, 2017 and August 11, 2017, BMW reviewed technical information and other documentation, to understand if the accessory turn signals conform to FMVSS 108, and to identify if any BMW motorcycle models might also be affected.

On August 11, 2017, BMW determined that the dealer accessory turn signals do not conform to FMVSS 108, and that certain BMW motorcycle models could also be affected.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

## Description of Remedy :

Description of Remedy Program : Owners of all potentially affected motorcycles will be contacted and instructed that if they have purchased the accessory turn signals, then they should make an appointment with their authorized BMW motorcycle dealer to have the turn signal lamps replaced.

How Remedy Component Differs from Recalled Component : Recall Component: Accessory Turn Signals: p/n(s): 7 708 048, 7 710 574, 7 710 575, 7 710 576, 7 714 326, 8 522 499, 8 522 500, 8 522 501, 8 522 502, 8 522 503

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : NR  
Planned Dealer Notification Date : AUG 18, 2017 - NR  
Planned Owner Notification Date : OCT 09, 2017 - NR

## Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR  
Address : NR  
NR  
Country : NR  
Company Phone : NR

\* NR - Not Reported