#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 17V-026

**Manufacturer Name:** Subaru of America, Inc.

Submission Date: AUG 22, 2017 NHTSA Recall No.: 17V-026 Manufacturer Recall No.: TKB-17



#### **Manufacturer Information:**

Manufacturer Name: Subaru of America, Inc.

Address: P.O. Box 6000

Cherry Hill NJ 08034-6000

Company phone: 856-488-8500

# **Population:**

Number of potentially involved : 69,529 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2005-2006 Subaru Baja

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Not all vehicles in the specified production date range are affected by this recall. This

recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already

covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.

Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.

Production Dates: APR 27, 2004 - APR 12, 2006

Vehicle 2: 2009-2009 Subaru Forester

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: Not all vehicles in the specified production date range are affected by this recall. This

recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators

containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already

covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.

Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.

Production Dates: DEC 03, 2007 - MAR 31, 2009

# **Part 573 Safety Recall Report**

17V-026

Page 2

VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential		
	GAS Not all vehicles i recall affects Tal	S in the specified kata Non-Desice	cated Fr	ontal Passenger-side A	ir Bag Inflators		
	containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.  Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.						
	Impreza include	s WRX and S11.					
Production Dates :							
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Descriptive Information :	Not all vehicles in the specified production date range are affected by this recall. This recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.  Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.						
Production Dates : VIN Range 1 :		APR 06, 2009 NR	End:	NR	☐ Not sequential		
Vehicle 5:	2009-2009 Suba	aru Legacy					
· -	LIGHT VEHICLE	S					
Body Style : Power Train :							
Descriptive Information :	Not all vehicles i recall affects Tal containing Phase covered under N	kata Non-Desico e Stabilized Am IHTSA Campaig	cated Fr moniun n Numl	tion date range are affe contal Passenger-side A n Nitrate for Zone B, for pers 14V763, 15V323 a emperature cycling and	ir Bag Inflators r vehicles not already nd 16V359.		

	includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.						
Production Dates :	IAN 30 2008 - A	PR 09 2009					
		NR	End:	ND	☐ Not cognontial		
VIN Range 1:	begin.	INIC	Ena .	IVIC	☐ Not sequential		
Vehicle 6:	2009-2009 Suba	ru Outback					
Vehicle Type :	LIGHT VEHICLES	S					
Body Style :							
Power Train :							
Descriptive Information :	Not all vehicles in the specified production date range are affected by this recall. This recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.  Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.						
Production Dates :	IAN 30 2008 - A	PR 09 2009					
VIN Range 1:		NR	End:	ND	☐ Not sequential		
VIIV Range 1.	Degin .	TVIC	Liid .	TVIC	Not sequential		
Vehicle 7:	2006-2009 Suba	ru Impreza					
	LIGHT VEHICLES	-					
V -	STATIONWAGO						
Power Train :							
Descriptive Information :	Not all vehicles in the specified production date range are affected by this recall. This recall affects Takata Non-Desiccated Frontal Passenger-side Air Bag Inflators containing Phase Stabilized Ammonium Nitrate for Zone B, for vehicles not already covered under NHTSA Campaign Numbers 14V763, 15V323 and 16V359.  Zone B includes states with moderate temperature cycling and absolute humidity. It includes: Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.  Impreza includes WRX and STI.						
	includes: Arizon Kentucky, Maryl Carolina, Ohio, C	states with mod a, Arkansas, De and, Missouri, I klahoma, Penn	derate t laware, Nebrask sylvani	emperature cycling an District of Columbia, I a, Nevada, New Jersey	d absolute humidity. It llinois, Indiana, Kansas, , New Mexico, North		
	includes: Arizon Kentucky, Maryl Carolina, Ohio, O Impreza include	states with mod a, Arkansas, De and, Missouri, I oklahoma, Penn s WRX and STI.	derate t laware, Nebrask sylvani	emperature cycling an District of Columbia, I a, Nevada, New Jersey	d absolute humidity. It llinois, Indiana, Kansas, , New Mexico, North		
Production Dates :	includes: Arizon Kentucky, Maryl Carolina, Ohio, O Impreza include JUN 16, 2005 - M	states with moda, Arkansas, De and, Missouri, I klahoma, Penn s WRX and STI.	derate t laware, Nebrask sylvani	emperature cycling an District of Columbia, I a, Nevada, New Jersey a, Tennessee, Virginia,	d absolute humidity. It llinois, Indiana, Kansas, , New Mexico, North and West Virginia.		
Production Dates : VIN Range 1 :	includes: Arizon Kentucky, Maryl Carolina, Ohio, O Impreza include JUN 16, 2005 - M	states with mod a, Arkansas, De and, Missouri, I oklahoma, Penn s WRX and STI.	derate t laware, Nebrask sylvani	emperature cycling an District of Columbia, I a, Nevada, New Jersey a, Tennessee, Virginia,	d absolute humidity. It llinois, Indiana, Kansas, , New Mexico, North		

## **Description of Defect:**

Description of the Defect: Takata has submitted DIR 17E-002 (Zone B) in accordance with the terms

specified in the May 4, 2016 Amendment to the November 3, 2015 Consent

Order in EA15-001.

Subaru is submitting this DIR in accordance with section 46 of Coordinated

Remedy Order.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Activation of a non-desiccated ammonium nitrate inflator with degraded

propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at

high speed, which may result in injury or death to vehicle occupants.

Description of the Cause: Based upon Takata's investigation to date, the propellant wafers in some of the

subject inflators may degrade over time, which could lead to overaggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may

cause the inflator body to rupture.

Identification of Any Warning None

that can Occur:

## **Supplier Identification:**

## **Component Manufacturer**

Name: Takata Corporation

Address: Tokyo Front Terrace 19F

2-3-14 Higashishinagawa Shinagawa-ku, Tokyo FOREIGN STATES 140-0002

Country: Japan

#### **Chronology:**

November 3, 2015 - NHTSA and Takata entered into a Consent Order in EA15-001 to resolve issues raised in that investigation, to mitigate and control risks of harm, and to promote public safety.

May 4, 2016 - NHTSA and Takata entered into an Amendment to the November 3, 2015 Consent Order. As stated in that Amendment, on the basis of testing and analysis conducted by Takata and by independent research organizations, NHTSA has concluded that, "at some point in the future all non-desiccated frontal Takata PSAN inflators will reach a threshold level of degradation that could result in the inflator becoming unreasonably dangerous." As a result of this conclusion, and pursuant to Paragraph 29 of the November 3, 2015 Consent Order, NHTSA ordered Takata to file certain defect information reports ("DIR"), in accordance with the schedule set forth in Paragraph 14 of the Amendment.

May 16, 2016 - As specified in that schedule, Takata submitted the DIR.

May 20, 2016 - Subaru has determined to launch recall according to Section 46 of Coordinated Remedy Order.

January 3, 2017 - As specified in that schedule, Takata submitted the DIR.

January 10, 2017 - Subaru has determined to launch recall according to Section 32 of 3rd amended Coordinated Remedy Order.

## **Description of Remedy:**

Description of Remedy Program: The remedy plan calls for dealers to replace the passenger airbag inflator.

How Remedy Component Differs NR from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: If parts supply is sufficient, Subaru will send owner notification letters

advising the customer to schedule a repair. If parts supply is insufficient, Subaru will send interim notification letters advising the customer they

are affected and will be re-notified when parts supply improves.

On March 6, 2017, owner notification letters were mailed to affected owners of 2009 Legacy and Outback vehicles advising parts are available.

All other affected owners were mailed interim notification letters advising the owners that they are affected and will be re-notified when

parts supply improves.

Planned Dealer Notification Date: JAN 13, 2017 - JAN 13, 2017

Planned Owner Notification Date: MAR 06, 2017 - MAR 06, 2017

<sup>\*</sup> NR - Not Reported