

Part 573 Safety Recall Report

17V-049

Manufacturer Name : Autocar Industries, LLC**Submission Date :** JAN 23, 2017**NHTSA Recall No. :** 17V-049**Manufacturer Recall No. :** ACTT-1701**Manufacturer Information :**

Manufacturer Name : Autocar Industries, LLC

Address : 551 South Washington Street
Hagerstown IN 47346

Company phone : 765-489-5499

Population :

Number of potentially involved : 29

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2017 Autocar Xspotter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Missing dimmer switch to adjust dash illumination.

Production Dates : JUL 14, 2015 - DEC 07, 2016

VIN Range 1 : Begin : 516H4GB26GH220716 End : 516H4GB29HH223532 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The subject vehicles were produced without a dimmer switch to adjust the light intensity of interior lamps, controls, and indicators as required per FMVSS 101.

FMVSS 1 : 101 - Control and displays

FMVSS 2 : NR

Description of the Safety Risk : The driver would not be able to adjust the brightness of interior lamps, controls, and indicators as required per FMVSS 101.

Description of the Cause : The subject vehicles had an incorrect Bill of Materials.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

11 January 2017 - Production reported lack of dimmer switch for on road vehicle. 13 January 2017 - Investigation started. 16 January 2017 - Autocar decided to release a recall.

Description of Remedy :

Description of Remedy Program : Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter which will describe the defect and provide instructions for scheduling repair of the vehicle at no cost to the owner.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : 13 January 2017 - Containment was initiated at the manufacturing plant and additional verification process put in place.

Recall Schedule :

Description of Recall Schedule : Owner notification letters will begin and end on 10 March, 2017.
Distributor notification will begin and end on 10 March, 2017.
Planned Dealer Notification Date : MAR 10, 2017 - MAR 10, 2017
Planned Owner Notification Date : MAR 10, 2017 - MAR 10, 2017

* NR - Not Reported