

# Part 573 Safety Recall Report

# 17V-147

**Manufacturer Name :** Keystone RV Company

**Submission Date :** MAR 07, 2017

**NHTSA Recall No. :** 17V-147

**Manufacturer Recall No. :** 17-279



## Manufacturer Information :

**Manufacturer Name :** Keystone RV Company

**Address :** PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

**Company phone :** 574-535-2100

## Population :

**Number of potentially involved :** 30

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2017-2017 Keystone Cougar

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Cougars within the production date range.

**Production Dates :** FEB 24, 2017 - FEB 27, 2017

**VIN Range 1 : Begin :** 4YDT30R20HV508117 **End :** 4YDF25R29HV508128  Not sequential

**Vehicle 2 :** 2017-2017 Keystone Laredo

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Laredos within the production date range.

**Production Dates :** FEB 24, 2017 - FEB 28, 2017

**VIN Range 1 : Begin :** 4YDT33023HV601485 **End :** 4YDT33121HV601502  Not sequential

## Description of Defect :

**Description of the Defect :** It has been decided that the vehicles in the recall population were manufactured with two carbon monoxide (CO) detectors instead of one smoke detector and one carbon monoxide detector.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** In the event of a fire, the lack of a smoke detector leads to an increased risk of personal injury and property damage.

**Description of the Cause :** The CO detector resembles the smoke detector.

Identification of Any Warning that can Occur : Unit has two detectors for CO and no smoke detector.

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

March 1, 2017 – Manufacturing discovered incorrect part installed.  
March 2, 2017 – Investigation and scope completed.

## Description of Remedy :

Description of Remedy Program : The remedy is to inspect to see if incorrect detector was installed and replace if necessary.

How Remedy Component Differs from Recalled Component : The replaced detector will be for smoke detection.

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

## Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : MAR 17, 2017 - MAR 17, 2017

Planned Owner Notification Date : MAR 17, 2017 - MAR 17, 2017

\* NR - Not Reported