

Part 573 Safety Recall Report**17V-284****Manufacturer Name :** Thor Motor Coach**Submission Date :** APR 27, 2017**NHTSA Recall No. :** 17V-284**Manufacturer Recall No. :** FL723AB**Manufacturer Information :****Population :**

Manufacturer Name : Thor Motor Coach

Number of potentially involved : 4

Address : PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46516

Company phone : 877-500-1020

Vehicle Information :

Vehicle 1 : 2015-2015 Tuscany All

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : According to Daimler Trucks North America, on certain motorhome chassis equipped with a certain adjustable foot pedal, the brake activation signal to the brake lights and to certain towed devices may not deactivate when the motorhome service brakes are released.

This may cause the motorhome brake lights to potentially remain illuminated, and additionally may cause the brakes on the towed device to remain engaged, depending on brake configuration. A towed device with incorrectly operating brakes could increase the risk of a crash.

Production Dates : JUL 28, 2016 - AUG 08, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : On certain motorhome chassis equipped with a certain adjustable foot pedal, the brake activation signal to the brake lights and to certain towed devices may not deactivate when the motorhome service brakes are released. This may cause the motorhome brake lights to potentially remain illuminated, and additionally may cause the brakes on the towed device to remain engaged, depending on brake configuration.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : . A towed device with incorrectly operating brakes could increase the risk of a crash.

Description of the Cause : On certain motorhome chassis equipped with a certain adjustable foot pedal, the brake activation signal to the brake lights and to certain towed devices may not deactivate when the motorhome service brakes are released.

Identification of Any Warning that can Occur : na

Supplier Identification :**Component Manufacturer**

Name : Daimler Trucks North America LLC

Address : 804 Mittel Dr
Wood Dale ILLINOIS 60191

Country : United States

Chronology :

November 2016 – January 2017 – FCCC requested updated dealer and retail owner information on a number of units built on their chassis

April 2017 – While preparing Quarterly Reports, TMC discovered that FCCC had released the recall and started notifying dealers and retail owners without notification to TMC.

Description of Remedy :

Description of Remedy Program : DTNA will modify the affected assembly. Repairs will be performed by Daimler Trucks North America authorized Service facilities

How Remedy Component Differs from Recalled Component : na

Identify How/When Recall Condition was Corrected in Production : unknown

Recall Schedule :

Description of Recall Schedule : Daimler and FCCC have already notified dealers and owners

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported