

# Part 573 Safety Recall Report

# 17V-378

**Manufacturer Name :** Newmar Corporation**Submission Date :** JUN 14, 2017**NHTSA Recall No. :** 17V-378**Manufacturer Recall No. :** 17012**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 210

Address : 355 North Delaware Street

Estimated percentage with defect : 100 %

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Vehicle Information :**

Vehicle 1 : 2012-2015 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the retaining ring on the starter shaft may break, without warning, allowing the shaft to extend beyond the starter motor. The motor could continue to be energized and overheat or eventually be subject to an over current condition. Overheating or an over current condition could increase the risk of a fire. Correction: The starter will be replaced free of charge.

Production Dates : JAN 27, 2011 - JUN 23, 2014

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2012-2015 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the retaining ring on the starter shaft may break, without warning, allowing the shaft to extend beyond the starter motor. The motor could continue to be energized and overheat or eventually be subject to an over current condition. Overheating or an over current condition could increase the risk of a fire. Correction: The starter will be replaced free of charge.

Production Dates : JAN 27, 2011 - JUN 23, 2014

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

**Description of Defect :**

Description of the Defect : On certain motorhomes, the retaining ring on the starter shaft may break, without warning, allowing the shaft to extend beyond the starter motor. The motor could continue to be energized and overheat or eventually be subject to an over current condition. Overheating or an over current condition could increase the risk of a fire. Correction: The starter will be replaced free of charge.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The starter motor could continue to be energized and overheat or eventually be subject to an over current condition. Overheating or an over current condition could increase the risk of a fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

On Monday, June 12th 2017, Spartan Motors notified Newmar Corporation the Prestolite Starter was defective. June 14th, 2017 Newmar is giving notice to NHTSA.

**Description of Remedy :**

Description of Remedy Program : The starter will be replaced free of charge

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 13, 2017 - AUG 13, 2017

Planned Owner Notification Date : AUG 13, 2017 - AUG 13, 2017

\* NR - Not Reported