

# Part 573 Safety Recall Report

# 17V-383

**Manufacturer Name :** Triple E Recreational Vehicles

**Submission Date :** JUN 16, 2017

**NHTSA Recall No. :** 17V-383

**Manufacturer Recall No. :** CA #8645-1



## Manufacturer Information :

**Manufacturer Name :** Triple E Recreational Vehicles

**Address :** PO Box 1230 Winkler MB

Canada 00 R6W 4C4

**Company phone :** 204-325-4361

## Population :

**Number of potentially involved :** 26

**Estimated percentage with defect :** 100 %

## Vehicle Alterer Information :

**Vehicle 1 :** 2016-2017 WONDER W24MB

**Descriptive Information :** THE FORD TRANSIT CHASSIS FRAME EXTENSION ADAPTER DOES NOT HAVE 4 (FOUR) M12 X 90 MM GRADE 10.9 BOLTS INSTALLED FOR EXTRA RIGIDITY FOR THE FRAME EXTENSION.

**Production Dates :** DEC 29, 2015 - MAR 20, 2017

## Description of Noncompliance :

**Description of the Noncompliance :** THE FRAME EXTENSION ADAPTER DOES NOT HAVE 4 (FOUR) M12 X 90MM GRADE 10.9 BOLTS INSTALLED.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** IF TOWING CAPACITY IS REACHED OR EXCEEDED, FRAME AND / OR FRAME EXTENSION STRUCTURE COULD DISTORT. NO SAFETY RISK INVOLVED.

**Description of the Cause :** FORD MOTOR COMPANY DID NOT INSTALL THE BOLTS IN THE FRAME EXTENSION AS INDICATED IN THEIR TRANSIT UPFITTER MANUAL.

**Identification of Any Warning that can Occur :** NR

## Supplier Identification :

### Component Manufacturer

**Name :** NR

**Address :** NR

NR

**Country :** NR

**Chronology :**

AN IN-HOUSE INSPECTION OF QUALITY CONTROL WAS PERFORMED AND WAS NOTICED IN THE PRODUCTION STAGES.

**Description of Remedy :**

Description of Remedy Program : DEALERS & RETAIL OWNERS ARE ASKED TO FOLLOW THE INSTRUCTIONS PROVIDED TO INSTALL THE 4 (FOUR) M12 X 90MM GRADE 10.9 BOLTS. IF THE RETAIL OWNER CHOOSES TO HAVE A SERVICING CENTER PERFORM THE RECALL, THE RETAIL OWNER WILL BE REIMBURSED OR THE SERVICING CENTER WILL BE PAID DIRECTLY BY TRIPLE E RV. THE DEALER WILL SUBMIT A WARRANTY CLAIM FOR THE TIME ALLOTTED TO PERFORM THE RECALL.

How Remedy Component Differs from Recalled Component : THE FRAME WILL HAVE THE 4 (FOUR) BOLTS INSTALLED IN THE FRAME IN FRONT OF THE EXTENSION.

Identify How/When Recall Condition was Corrected in Production : A PHYSICAL CHECK OF THE CHASSIS FRAME USING THE TRANSIT UPFITTER MANUAL WAS PERFORMED AND NOTICED THE BOLTS MISSING FROM THE CHASSIS' SUPPLIED BY FORD MOTOR COMPANY.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUN 22, 2017 - JUN 23, 2017

Planned Owner Notification Date : JUN 22, 2017 - JUN 23, 2017

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

\* NR - Not Reported