

Part 573 Safety Recall Report

17V-413

Manufacturer Name : Newmar Corporation**Submission Date :** JUN 29, 2017**NHTSA Recall No. :** 17V-413**Manufacturer Recall No. :** 17015**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 4

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Estimated percentage with defect : 100 %

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2018-2018 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the drive gear on the fuel pump may spin loose on the drive shaft, resulting in loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted. An unexpected engine stall without the ability to restart may increase the risk of a crash. Correction: the fuel pump will be replaced at no charge to the customer.

Production Dates : JAN 16, 2017 - MAR 03, 2017

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2018-2018 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the drive gear on the fuel pump may spin loose on the drive shaft, resulting in loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted. An unexpected engine stall without the ability to restart may increase the risk of a crash. Correction: the fuel pump will be replaced at no charge to the customer.

Production Dates : JAN 16, 2017 - MAR 03, 2017

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2018-2018 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the drive gear on the fuel pump may spin loose on the drive

Descriptive Information : shaft, resulting in loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted. An unexpected engine stall without the ability to restart may increase the risk of a crash. Correction: the fuel pump will be replaced at no charge to the customer.

Production Dates : JAN 16, 2017 - MAR 03, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the drive gear on the fuel pump may spin loose on the drive shaft, resulting in loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted. An unexpected engine stall without the ability to restart may increase the risk of a crash. Correction: the fuel pump will be replaced at no charge to the customer.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The engine may stall without warning and cannot be restarted. An unexpected engine stall without the ability to restart may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 6/28/17 Spartan Motors gave notice to Newmar regarding a safety defect. On 6/29/17 Newmar is giving notice to NHTSA.

Description of Remedy :

Description of Remedy Program : The fuel pump will be replaced at no charge to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 28, 2017 - AUG 28, 2017

Planned Owner Notification Date : AUG 28, 2017 - AUG 28, 2017

* NR - Not Reported