

Part 573 Safety Recall Report

17V-420

Manufacturer Name : Newmar Corporation**Submission Date :** JUN 30, 2017**NHTSA Recall No. :** 17V-420**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 1,289

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2014-2018 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the driver and passenger power night shades may be operated using the remote when the ignition is in the ON position. If the ignition is on and the remote night shade button is pushed, the night shades can come down, blocking the side views of the driver, which may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will install a relay to disable the operation of the driver and passenger night shade by the remote when the ignition is in the ON position.

Production Dates : FEB 12, 2013 - MAY 16, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2015-2017 Newmar Ventana

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the driver and passenger power night shades may be operated using the remote when the ignition is in the ON position. If the ignition is on and the remote night shade button is pushed, the night shades can come down, blocking the side views of the driver, which may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will install a relay to disable the operation of the driver and passenger night shade by the remote when the ignition is in the ON position.

Production Dates : FEB 12, 2013 - MAY 16, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the driver and passenger power night shades may be operated using the remote when the ignition is in the ON position. If the ignition is on and the remote night shade button is pushed, the night shades can come down, blocking the side views of the driver, which may increase the risk of a crash causing injury and/or property damage. Correction: Dealers will install a relay to disable the operation of the driver and passenger night shade by the remote when the ignition is in the ON position.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the ignition is on and the remote night shade button is pushed, the night shades can come down, blocking the side views of the driver, which may increase the risk of a crash causing injury and/or property damage.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 6/26/2017 Newmar discovered a safety defect with night shades. On 6/30/2017, Newmar is giving notice to NHTSA of a safety defect.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 29, 2017 - AUG 29, 2017

Planned Owner Notification Date : AUG 29, 2017 - AUG 29, 2017

* NR - Not Reported