

# Part 573 Safety Recall Report

# 17V-464

**Manufacturer Name :** Tremcar**Submission Date :** AUG 11, 2017**NHTSA Recall No. :** 17V-464**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Tremcar

Address : 790 Montrichard

St. Jean-sur-Richelieu 00 J2X5G4

Company phone : 3477822

**Population :**

Number of potentially involved : 3

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2008-2017 Tremcar 2800ft3 Dry Bulk Quad

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Only 3 bumpers have been imported into the US. The rest of the vehicle and similar vehicle population was sold and for use in Canada.

Production Dates : JUN 01, 2008 - JUN 13, 2017

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2008-2008 Tremcar 1350ft3 B-train pup

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Only unit 6525 makes use of the rear impact guard in question

Production Dates : JUN 01, 2008 - AUG 01, 2008

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2014-2014 Tremcar 1625ft3 Vac tandem

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Only unit 14071 makes use of the rear impact guard in question

Production Dates : OCT 01, 2014 - NOV 30, 2014

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 4 : 2016-2016 Tremcar 2300ft3 Quad

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Only unit 15934 makes use of the rear impact guard in question

Production Dates : JUL 07, 2015 - SEP 01, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Noncompliance :

Description of the Noncompliance : The rear impact guard has failed a compliance test at position p1

FMVSS 1 : 223 - Rear impact guards

FMVSS 2 : NR

Description of the Safety Risk : The rear impact guard does not adequately perform its duty

Description of the Cause : Not yet determined

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

Tremcar was asked to provide 3 sample Rear Impact Guards for compliance testing in January 2017.

The result of that test was provided by NHTSA in a request for information letter OA-223-170511 on June 14, 2017.

Upon analysis of the results it was determined that there is a non-compliance on July 14, 2017

## Description of Remedy :

Description of Remedy Program : Not yet been determined

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Not yet been determined

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported